

The Boeing Company  
P.O. Box 516  
St. Louis, MO 63166-0516  
(314) 232-0232

RECEIVED

MAY 07 2012

AWMD/WRAP-KNRP

May 1, 2012  
107A-6658-JWH

Mr. Richard Nussbaum, Chief  
Permits Section  
Hazardous Waste Program  
Missouri Department of Natural Resources  
205 Jefferson Street  
P.O. Box 176  
Jefferson City, MO 65102



Encl: Corrective Action Quarterly Progress Report-First Quarter 2012

Dear Mr. Nussbaum:

The enclosed Quarterly Progress Report is submitted as required by Section XI of the Corrective Action Conditions of the Hazardous Waste Management Facility Permit, Number MOD 000 818 963. Two copies of the report will also be submitted to the U.S. EPA, Region VII as required under the terms of the permit.

Please contact me should you need additional information.

Sincerely,

A handwritten signature in cursive script that reads "Joe Haake".

Joe Haake  
Environmental Scientist  
(314) 777-9181

cc: Bruce Stuart, MDNR  
Christine Kump-Mitchell, MDNR  
Amber Whisnant, U.S. EPA Region 7

RCRA



516846

## **Quarterly Progress Report for First Quarter 2012**

### **Description of the work completed**

Received comments on the Interim Measures Workplan from MDNR and St. Louis Lambert International Airport in January.

Submitted the Focused Corrective Measures Study to MDNR and U.S. EPA in February.

Conducted groundwater sampling and gauging in February.

Submitted response to comments and revised Interim Measures Workplan to MDNR and U.S. EPA in March.

### **Summary of all findings**

None

### **Summary of all problems or potential problems and actions taken to rectify problems**

Groundwater elevations at MW3A and RC15 in the scrap dock cutting oil drainage area on GKN property are 2 feet shallower compared to the wells to the east. Also, the interface probe used to measure the water level at these wells was covered in black liquid upon retrieval. This suggests that there is a possible leak of the underground sewer line which drains the cutting fluids from the area. Boeing is working with GKN to investigate.

### **Projected work for the next reporting period**

Award a contract for the interim measures work.

Prepare and submit groundwater sampling report.

### **Instances of noncompliance with the corrective actions of the permit**

None

## **Quarterly Progress Report for First Quarter 2012**

### **Description of the work completed**

Received comments on the Interim Measures Workplan from MDNR and St. Louis Lambert International Airport in January.

Submitted the Focused Corrective Measures Study to MDNR and U.S. EPA in February.

Conducted groundwater sampling and gauging in February.

Submitted response to comments and revised Interim Measures Workplan to MDNR and U.S. EPA in March.

### **Summary of all findings**

None

### **Summary of all problems or potential problems and actions taken to rectify problems**

Groundwater elevations at MW3A and RC15 in the scrap dock cutting oil drainage area on GKN property are 2 feet shallower compared to the wells to the east. Also, the interface probe used to measure the water level at these wells was covered in black liquid upon retrieval. This suggests that there is a possible leak of the underground sewer line which drains the cutting fluids from the area. Boeing is working with GKN to investigate.

### **Projected work for the next reporting period**

Award a contract for the interim measures work.

Prepare and submit groundwater sampling report.

### **Instances of noncompliance with the corrective actions of the permit**

None